









# VTA-SYMP TOMS

FAILURE:  $t/R \leq 0.3$



RIBS INDICATE CRACKS

DRILLING TO MEASURE (t)



Prof. Dr. C. Mattheck, Dr. K. Bethge  
 Forschungszentrum Karlsruhe GmbH  
 Institut für Materialforschung II  
 Postfach 3640  
 D-76021 Karlsruhe

